AIRCRAFT
TECHNICAL RECORD

Section 1. AIRFRAME LOG

AIRCRAFT

1. Nationality and Registration:	N895PA
2. Manufacturer's designation:	DA 62
3. Manufacturer's Serial Number:	62.C063
4. Type Approval or Specification Number:	A00012NY
5. Date of Manufacture:	2023
6. Aircraft Inspections cycle:	

DIAMOND AIRCRAFT INDUSTRIES INC.
D.O.T. APPROVED MANUFACTURER #161-93

Registration:	N895PA
AC Serial Number:	62.C063
LH Engine Serial Number:	E4P-C-06308
RH Engine Serial Number:	E4P-C-06292
LH Prop Serial Number:	230711
RH Prop Serial Number:	230712
Airframe Total Time:	5.3 HRS

- Total Time **Airframe** Brought forward from Production Test Flight Journey Log (DAI - Form Q-224): 5.3 HRS
- Compass Swing Performed:
  - Date: AUGUST 31 2023
  - Next Due: AUGUST 2024

FOR	N	30	60	E	120	150
STEER	360	030	060	091	120	150
FOR	S	210	240	W	300	330
STEER	180	209	239	270	300	331

- Static Pressure system and Primary Altimeter (G1000) have been inspected and tested in accordance with CAR Standard 571, Appendix B and 14 CFR 91.411:
  - Test Date: AUGUST 11 2023
  - Next Due: AUGUST 2025
- Stand By Altimeter:
  - Factory Test Date: MARCH 23 2023
  - Next Due: MARCH 2025
- ATC Transponder & Altitude Reporting System(s) have been tested in accordance with CAR Standard 571, Appendix F and 14 CFR 91.217: & 91.413:
  - Test Date: AUGUST 12 2023
  - Next Due: AUGUST 2025
  - Programmed Registration: N895PA
  - Hex Code: N/A (USA Registration)
- The ELT was tested and inspected in accordance with CAR Standard 571, Appendix G and 14 CFR 91.207(d):
  - Manufacturers Cert. date: 11/ 22 (WW/YY)
  - Installation Inspected: SEPTEMBER 29 2023
  - Battery due: SEPTEMBER 2029
  - Next ELT inspection due: SEPTEMBER 2024
  - ELT Programmed:
    - REG: N895PA
    - Hex ID: N/A
    - Country: 366 (USA)
    - 15 Hex ID: ADC6498C0C1B781
- Garmin G1000 NXi Installation:
  - System: 3787.02
  - Checklist File: N/A
  - Basemap Land 5.20
  - SafeTaxi Data: Expires 30-NOV-2023
  - Terrain Data: 3.00
  - Obstacle Data: Expires 30-NOV-2023
  - Navigation Data: Expires 2-NOV-2023
  - Apt Directory: Expires 30-NOV-2023
  - FliteCharts Data: Expires 2-NOV-2023
  - IFR/VFR charts: Date: 5-OCT-2023

DA Q 8
Inspector

OCT 16 2023
date

(Continued next page)

DIAMOND AIRCRAFT INDUSTRIES INC.
D.O.T. APPROVED MANUFACTURER #161-93

Registration:	N895PA
AC Serial Number:	62.C063
LH Engine Serial Number:	E4P-C-06308
RH Engine Serial Number:	E4P-C-06292
LH Prop Serial Number:	230711
RH Prop Serial Number:	230712
Airframe Total Time:	5.3 HRS

- Following limitations as per DA 62 AMM Chapter 4,5 (subject to change with revision):

Component	Hours	Years	Next Due:
ECU backup batteries LH/RH	-N/A-	1 yr. +/- 30 days	AUGUST 2024
Bonding system and static discharging system.	1000 +/- 50	4 yrs. +/- 60 days	1000 or AUGUST 2027
Emergency battery package (if MAM 62-002 is NOT installed)	-N/A-	2 yrs	N/A; MAM62-002 Incorporated.

- The following STC's are incorporated:
  - FAA STC No. SA00018IB (Beringer wheel and brake system)
- THIS AIRCRAFT WAS INSPECTED FOR CONFORMITY TO APPLICABLE COMPANY RELEASED DOCUMENTS (DRAWINGS, SPECIFICATIONS, CONCESSIONS).
- I HEREBY CERTIFY THAT THIS AIRCRAFT CONFORMS TO FAA TYPE CERTIFICATE A00012NY Rev. No. 2, AND IS IN A FIT AND SAFE STATE FOR FLIGHT.
- **Bi-weekly AWD check carried out to current revision 2023-21 all applicable AD's complied with**
- The work described above was carried out in accordance with the applicable Standard of Airworthiness.

DA Q 8
Inspector

OCT 16 2023
date

(Intentionally left blank below this point)

Section 1: Airframe Log

DATE	AIR TIME				LANDINGS / CYCLES		DETAILS OF TASK (INSPECTION, REPAIRS & REPLACEMENT)
	DAILY TOTAL		TOTAL		DAILY TOTAL	TOTAL	
/ /	HRS	MIN	HOURS	MIN			
CARRIED FORWARD							

Diamond AIRCRAFT

DIAMOND AIRCRAFT IND.
D.O.T. APPROVED MAINTENANCE ORGANIZATION161-93

Registration:	N895PA	AC Serial Number:	62.C063
Airframe Total Time:	8.9 Hrs	Work Order:	SO074532
Engine LH SN:	E4P-C-06308	Engine RH SN:	E4P-C-06292
Engine LH TT:	8.9 Hrs	Engine RH TT:	8.9 Hrs
Prop LH SN:	230711	Prop RH SN:	230712
Prop LH TT:	8.9 Hrs	Prop RH TT:	8.9 Hrs

The Following Maintenance was Performed:

- RH engine coolant level sensor replaced with new **P/N: D4D-9075-26-26.** Ground run and leak check carried out, found serviceable.
- LH and RH forward entry door handles adjusted as required.

The Maintenance Described has been performed IAW the Applicable Standard of Airworthiness

DIAMOND AIRCRAFT INDUSTRIES INC. ACA 68 AMO 161-93

ACA _____ Date: NOV 0 3 2023

MAKE: Diamond
MODEL: DA62
S/N: 62.C063
REG. NO: 895PA
WORK ORDER
10716-06-2024

Premier Aircraft Service

Premier Aircraft Service,. Inc.
5540 NW 23rd Avenue Hangar 14
Fort Lauderdale, FL 33309
Phone: (954) 334-2393

DATE: 6/24/2024
A/C TSN: 111.8
TACH: 111.8

Airframe Entries

(2) REPLACED RH AUX FUEL TANK FILLER NECK ASSY O-RING WITH NEW P/N OR75.79X3.53-NBR AND FUEL DRAIN VALVE WITH NEW P/N CAV-180 IAW DA62 CH 28-10.
(4) REPLACED RUDDER TRIM CONTROL KNOB COIL SPRING WITH NEW P/N: D60-7613-10-50 AND RUDDER TRIM INDICATOR BACKGROUND ASSY WITH NEW P/N: D60-7813-18-00 IAW DA62 MM CH: 27-21. OPS CHECKED GOOD.
(10) INSTALLED CO-PILOT REMOVABLE CONTROL STICK WITH SERVICEABLE PART P/N: D67-2703-12-00X02 IAW OAM-62-025/c, DESIGN CHANGE ADVISORY 62-288, & DA-62 MM CH 27-10-00 AND SCHEMATIC DRAWING D67-9227-03-00. FLIGHT CONTROL AND AUTOPILOT GROUND CHECK OK, NO FAULTS NOTED.
(11) INSTALLED GSR-56 IRIDIUM SAT PHONE IAW DIAMOND OAM 62-015 FACTORY DWG.D67-3403-01-00_03, D67-9223-15-00, D67-2313-21-00, AND D67-2313-20-00. INSTALLED UNIT P/N: 011-02268-00 S/N: 1NZ010728 AND ANTENNA P/N:CI490-490 S/N: 694151. REVISED EQUIPMENT LIST AND WEIGHT AND BALANCE.

DATE: 6/24/2024 SIGNED: _____

EMMANUEL VICIOSO
CRS 9PIR402B

Work Order: 10716-06-2024

Printed by EBis 3 (datcomedia.com)

PAGE TOTALS							CARRY FORWARD to Top of Next Page

NAME/ SIGNATURE | LICENCE: AME or AMO/ACA

MAKE: Diamond
MODEL: DA62
S/N: 62.C063
REG. NO: 895PA
WORK ORDER: 10791-08-2024

Premier Aircraft Service

Premier Aircraft Service,. Inc.
5540 NW 23rd Avenue Hanger 14
Fort Lauderdale, FL 33309
Phone: (954) 334-2393

DATE: 9/17/2024
A/C TSN: 130.8
TACH: 130.8

Airframe Entries

(3) REMOVED, CLEANED, AND RE-INSTALLED RH FUEL LOW PRESS PUMP BYPASS CHECK VALVE. REPLACED RH FUEL FILTER WITH NEW P/N WK724_3. WORK DONE IAW DA62 MM CH 28-20. OPS CHECK GOOD
(5) REPAIRED RH DE-ICE LIGHT GROUND WIRING ON PLUG J2420 IAW AC43.13-1B CH 11. LIGHT OPS CHECKED GOOD.
(9) RESEALED RH AUX FUEL TANK FILLER NECK IAW DA62 AMM CH 28-10.

DATE: 9/17/2024 SIGNED: EMMANUEL VICIOSO
CRS 9PBR402B

Work Order: 10791-08-2024
Printed by EBis 3 (datcomedia.com)

MAKE: Diamond
MODEL: DA62
S/N: 62.C063
REG. NO: 895PA
WORK ORDER: 10835-10-2024

Premier Aircraft Service

Premier Aircraft Service,. Inc.
5540 NW 23rd Avenue Hangar 14
Fort Lauderdale, FL 33309
Phone: (954) 334-2393

DATE: 11/4/2024
A/C TSN: 131.7
TACH: 131.7

Airframe Entries

(3) C/W ANNUAL INSPECTION ON THIS AIRFRAME IAW 14 CFR PART 43, APPENDIX "D" USING DA62 MM CH 5 INSPECTION CHECKLIST AS A GUIDE. C/W FAR 91.207 D ELT INSPECTION AND FUNCTIONAL CHECK. ELT BATTERY EXPIRATION DATE: 9/2029. ADs CHECKED THROUGH CURRENT ON ATP.
(12) C/W ICA BERINGER BRAKES INSP IAW DOC# MM-ETSO-001. REPLACED LH AND RH BRAKE DISCS AND PADS WITH NEW P/N DSC-009.5(A) AND PQT-014(A) IAW DOC# MM-ETSO-001 AND DA62 MM CH 20-00 & 32-40.
(14) C/W 1 YR GFC700 AUTOPILOT MECHANICAL CHECK IAW DA62 MM CH 22-10.
(16) C/W 1 YR ECU BACKUP BATTERIES REPLACEMENT. INSTALLED NEW P/N NP7-12 IAW DA62 AMM CH 24-31.
(17) C/W 1 YR DEICE FLUID STRAINER CLEANING IAW DA-62 MM CH 30-00.
(19) SERVICED PROP ACCUMULATORS WITH NITROGEN IAW DA62 MM CH 61-20.
(20) REPLACED O-RING AND RESEALED LH AUX FUEL TANK FILLER CAP NECK IAW DA62 MM CH 28-10.
(24) REPLACED LH ELECTRIC FUEL PUMP LOWER FILTER GASKETS WITH NEW P/N DIN7603-A14X20X1.5AL IAW DA 62 MM CH 28-20. OPS CHECKED GOOD.
(25) SERVICED OXYGEN IAW DA 62 MM CH 25-10.
(26) COMPLIED WITH DIAMOND G1000NXI MSB-62-003 REV.9 PHASE3 SOFTWARE UPDATE 006-B3787-05. I/A/W GARMIN G1000NXI LINE MM 190-02631-00. ENABLED G1000 OPTIONS ENHANCED AFCS,SVT,CHART, AND GWX75. GROUND OP CHECK NORM NO FAULTS NOTED.

I CERTIFY THIS AIRFRAME, ENGINE, OR PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

DATE: 11/4/2024 SIGNED: EMMANUEL VICIOSO
CRS 9PBR402B

Work Order: 10835-10-2024
Printed by EBis 3 (datcomedia.com)

MAKE: Diamond
MODEL: DA62
S/N: 62.C063
REG. NO: 895PA
WORK ORDER: 10835-10-2024

Premier Aircraft Service

Premier Aircraft Service,. Inc.
5540 NW 23rd Avenue Hangar 14
Fort Lauderdale, FL 33309
Phone: (954) 334-2393

DATE: 11/4/2024
A/C TSN: 131.7
TACH: 131.7

Avionics Entries

(13) C/W ELT TEST AND INSPECTION IAW FAR 91.207-D, PAR 1-2-3-4 ON KANNAD ELT P/N: S1851501-02 S/N:TM0000278261 AND FOUND SATISFACTORY. ELT BATTERY DUE DATE: SEP/2029. HEX ID: ADC6498C0C1B781.

DATE: 11/4/2024 SIGNED: RAYMOND OCASIO
CRS 9PBR402B

Work Order: 10835-10-2024
Printed by EBis 3 (datcomedia.com)

Section 1: Airframe Log

DATE	AIR TIME		LANDINGS / CYCLES
/ /	DAILY TOTAL	TOTAL	DAILY

CARRIED FORWARD

(REPLACEMENT)

MAKE: Diamond
MODEL: DA62
S/N: 62.C063
REG. NO: 895PA
WORK ORDER
10835-10-2024

Premier Aircraft Service

Premier Aircraft Service,, Inc.
5540 NW 23rd Avenue Hangar 14
Fort Lauderdale, FL 33309
Phone: (954) 334-2393

DATE: 11/15/2024
A/C TSN: 132.8
TACH: 132.8

Airframe Entries

(29) POST MAINTENANCE OPERATIONAL FLIGHT PERFORMED BY FRANCISCO LOPEZ, RATED PILOT CERTIFICATE # 4027351 PER 14 CFR 91.407.
(30) REPLACED RH ELEC FUEL PUMP (B) WITH NEW P/N D64-9028-11-01-MOD IAW DA62 MM CH 28-20-00. OPS CHECK GOOD.

DATE: 11/15/2024 SIGNED:
EMMANUEL VICIOSO
CRS 9PRR402B

Work Order: 10835-10-2024
Printed by EBIS 3 (datcomedia.com)

MAKE: Diamond
MODEL: DA62
S/N: 62.C063
REG. NO: 895PA

Premier Aircraft Service

Premier Aircraft Service, Inc.
5540 NW 23rd Avenue Hangar 14
Fort Lauderdale, FL 33309

W/O #: 11205-09-2025
DATE: 09-11-2025
Airframe TT: 199.9
Tach: 199.9

Entries

3 REMOVED AND REPLACED BOTH A AND B ELECTRIC LOW FUEL PUMPS PN: D64-9028-11-01-MOD FOR RH ENGINE IAW DA62 M/M CH 28-20-00. OPS CHECKED GOOD. NO LEAKS DETECTED.

DATE: 09-11-2025 SIGNED:
Samuel Tavarez
License: A&P 3521895

WORK ORDER: 11205-09-2025
Printed by EBIS (EBISCloud.com)

MAKE: Diamond
MODEL: DA62
S/N: 62.C063
REG. NO: 895PA

Premier Aircraft Service

Premier Aircraft Service, Inc.
CRS: # 9PRR402B
5540 NW 23rd Avenue Hangar 14
Fort Lauderdale, FL 33309

W/O #: 11205-09-2025
DATE: 09-23-2025
Airframe TT: 202.8
Tach: 202.8

Airframe Entries

4 REMOVED BATTERY P/N RG24-15 S/N 41282222 FOR CAP TEST. FAILED AT 32%. INSTALLED NEW BATTERY P/N RG24-15 S/N 41436492 IAW DA62 MM CH 24-31-00. OPS CHECKED GOOD.
5 REPLACED LH & RH FUEL CAP O-RINGS WITH NEW P/N MS29513-338 & BS534 IAW DA62 MM CH 28-10.
6 REPLACED COPILOT STORM WINDOW LATCH BLOCK WITH NEW P/N 301.12.0115 AS REQUIRED.

DATE: 09-23-2025 SIGNED:
Emmanuel Vicioso
CRS: # 9PRR402B

WORK ORDER: 11205-09-2025
Printed by EBIS (EBISCloud.com)

PAGE TOTALS

CARRY FORWARD to Top of Next Page

MAKE: Diamond
MODEL: DA62
S/N: 62.C063
REG. NO: 895PA

Premier Aircraft Service, Inc.
CRS: # 9PRR402B
5540 NW 23rd Avenue Hangar 14
Fort Lauderdale, FL 33309

W/O #: 11270-11-2025
DATE: 01-05-2026
Airframe TT: 205.3
Tach: 205.3

ME/ ATURE

LICENCE: AME or AMO/ACA

Entries

2 C/W ANNUAL INSPECTION ON THIS AIRFRAME IAW 14 CFR PART 43, APPENDIX "D" USING DA62 MM INSPECTION CHECKLIST AS A GUIDE. C/W FAR 91.207 D ELT INSPECTION AND FUNCTIONAL CHECK. ELT BATTERY EXPIRATION DATE: 9/2029. ADs CHECKED THROUGH CURRENT ON ATP.

7 REPLACED RH STORM WINDOW HINGES WITH NEW P/N: 301.25.4105 AS REQUIRED.

8 CLEANED ELEVATOR TRIM FRICTION ROD IAW DA62 MM CH: 27-38-00. OPS CHECK GOOD.

15 C/W 1 YR 4 ECU BACKUP BATTERIES REPLACEMENT WITH PN: NP7-12 IAW DA 62 AMM CH 24-30-00.OPS CHECKED GOOD.

16 C/W ICA BERINGER BRAKES INSP IAW DOC# MM-ETSO-006

17 C/W 1 YR AUTOPILOT MECHANICAL CHECK. NO DEFECTS FOUND.

18 C/W DIAMOND MSB62-020 MIDDLE AND REAR PASSENGER SEAT LAP SAFETY BELT CONNECTION. NO DEFECTS FOUND.

19 C/W MANDATORY SERVICE BULLETIN NO. MSB 62-051 REV. 1 REPLACEMENT OF THE MAIN AND NOSE LANDING GEAR RETAINING RINGS.

20 C/W 1 YR MAIN BATTERY CAP TEST IAW DA62 MM CH: 25-31-00. NO FAULTS FOUND.

21 C/W 1 YR DE-ICE FLUID STRAINER CLEANING IAW DA62 MM CH: 30-00-00.

22 C/W ICA SAM MD302 STDBY INSTRUMENT INSPECTION IAW DOC NO. 9017782. NO DEFECTS NOTED.

23 UPON PRESSURE TEST, NO LEAKS FOUND AND SYSTEM IS FUNCTIONING AS REQUIRED ON RH ENGINE COOLANT SYSTEM.

24 CLEANED AND TREATED NOSE LG DOOR ATTACHMENT RODS WITH AV-30 AS REQUIRED.

25 CLEANED AND TREATED NOSE LG SPRING WITH AV-30 AS REQUIRED

26 INSTALLED NEW NOSE LG TORQUE LINK HARDWARE AND CENTERING UNIT HARDWARE IAW DA62 MM CH: 32-20-00.

27 REPLACED LH AND RH DOWNLOCK RODS ON MAIN GEAR WITH NEW P/N: D60-3237-41-00, SPRING WITH NEW P/N: Z-234I-MO, MLG HOOK ASSY WITH NEW P/N: D60-3237-51-00, AND ASSOCIATED HARDWARE IAW DA62 MM CH: 32-10-00.

28 CLEANED AND TREATED ALL STATIC WICKS AS REQUIRED.

29 UPDATED SOFTWARE ON MD302 P/N: 6420302-1 S/N: C23-11172 IAW CH: 34-20-00 AND MM 9017782.

30 CLEANED PILOT SIDE TAIL PITOT STATIC PORT IAW DA62 MM CH: 34-10-00.

31 REPLACED RH AND LH AUX FUEL TANK VENT SCREEN CIRCLIPS WITH NEW P/N: DIN472-12-INOX IAW DA62 MM CH: 28-20-00.

32 REPLACED LH AND RH ELECTRIC FUEL FEED PUMP LOWER HOLLOW BOLT GASKETS WITH NEW P/NS DIN7603-A14X20X1.5AL IAW DA 62 MM CH 28-20. LEAK CHECK GOOD.

33 CLEANED AND LUBRICATED GOTH LH AND RH FUEL CAPS LEVER SHAFTS AS REQUIRED.

34 CLEANED AND RESERVICED BOTH RH AND LH MLG DAMPNERS IAW DA 62 MM CH: 32-10-00. LEAK CHECK GOOD.

35 REPLACED PITOT MASS ATTACHMENT HARDWARE WITH NEW AS REQUIRED.

36 CLEANED AND TREATED RUDDER TRIM CONNECTING RODS AS REQUIRED.

37 CLEANED AND TREATED RIVNUT AND AURROUNDING HORIZONTAL STABILIZER BOTTOM AT ELEVATOR TRIM COVER RIVNUT AREA AS REQUIRED.

38 CLEANED AND TREATED PILOT YOKE STICK BEARING HARDWARE AS REQUIRED.

39 RESEALED LH AND RH PROPELLER BLADES DE-ICE BOOTS AS REQUIRED.

40 REINSTALLED LH AND RH FLAP & AILERON ROD END GROUND STRAP INTO PROPER POSITION IAW DA62 MM CH: 27-50-00.

41 CLEANED SURFACE CORROSION OFF GARMIN OAT PROBE AS REQUIRED.

42 REPLACED LH AND RH AUX FUEL TANK FUEL GRADE PLACARDS WITH NEW P/N: D67-1124-20-22 IAW DA62 AMM CH: 11.

43 PREPARED AND TOUCHUP PAINTED AROUND WINDSHIELD AND REAR PASSENGER WINDOWS IAW DIAMOND DA62 M/M CH 51.

44 PREP AND PAINTED REAR NACELL AUX COVER IAW DIAMOND DA62 M/M CH 51.

45 PREP AND PAINTED SEVERAL AREAS AROUND AIRCRAFT IAW DIAMOND DA62 M/M CH 51.

46 REPLACED RH AND LH MAIN FUEL TANK VENT SCREEN CIRCLIPS WITH NEW P/N: DIN472-12-INOX IAW DA62 MM CH: 28-20-00.

47 REPLACED LH MLG DAMPER INTERNAL SEALS AND ORINGS WITH NEW IAW DA62 MM CH: 32-10-00.

I CERTIFY THIS AIRFRAME, ENGINE, OR PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

DATE: 01-05-2026

SIGNED:
Samuel Tavarez
CRS: # 9PRR402B

WORK ORDER: 11270-11-2025
Printed by EBIS (EBISCloud.com)

Section 1: Airframe Log

DATE	AIR TIME				LANDINGS / CYCLES		DETAILS OF TASK (INSPECTION, REPAIRS & REPLACEMENT)
	DAILY TOTAL		TOTAL		DAILY TOTAL	TOTAL	
/ /	HRS	MIN	HOURS	MIN			
CARRIED FORWARD							

MAKE: Diamond
MODEL: DA62
S/N: 62.C063
REG. NO: 895PA

Premier Aircraft Service, Inc.
CRS: # 9PRR402B
5540 NW 23rd Avenue Hangar 14
Fort Lauderdale, FL 33309

W/O #: 11270-11-2025
DATE: 01-05-2026
Tach: 205.3

Entries

9 I CERTIFY THAT ALTIMETER, ALTITUDE REPORTER, TRANSPONDER AND STATIC SYSTEM TEST REQUIRED BY FAR 91.411 HAS BEEN COMPLETED. ALTIMETER HAS BEEN TESTED TO 20,000 FT. MAIN ALTIMETER: M/N GDC1 S/N 45S100133 STBY ALT SAM302 P/N: 6420302-1 S/N C23-11172.
I CERTIFY THAT THE TRANSPONDER M/N GTX1 S/N 3EH031422, TEST PER FAR 91.413 HAS BEEN COMPLETED. INSPECTION REPORTS ON FILE UNDER THIS W/O.

10 PERFORMED KANNAND 406 ELT OPS CHECK IAW FAR 91.207-D ON ELT P/N: S1851501-02 S/N: TM0000276261. BATTERY EXP DATE 09/2029 HEX ID: ADC6498C0C18781. OPS CHECKED GOOD.

DATE: 01-05-2026 SIGNED: Raymond Ocasio
CRS: # 9PRR402B

WORK ORDER: 11270-11-2025
Printed by EBIS (EBISCloud.com)

PAGE TOTALS							CARRY FORWARD to Top of Next Page