

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-I34R-1RF

PROPELLER S/N HK1176B

LOGBOOK # 1

[illegible]



Sensenich Propeller Service, Inc.

1142 Aviation Boulevard Gainesville, Ga. 30501

Phone (770)538-0444 Fax (770)538-0117 www.sensenichpropellers.com

Date of Balance: **2/17/09**

Aircraft: **Piper PA32R-300**

Work Order Number: **G12403**

Reg. No.: **N614DM**

Propeller Serial No: **HK1176B**


Tach: **397.6**

Final Balance: **.04**

C. Neal Jones

Repair Station S46R346N

This Propeller has been balanced using procedures outlined in manual:
Aces System to Propeller Balancing.

Date	Propeller TSN TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
				Pelican Aviation, Inc. Summerville SC 29483 08-01-09 N614DM Prop TSN 449.9 Inspected prop for condition and security <i>At the time of this inspection, I certify that this prop has been inspected in accordance with an ANNUAL inspection and was found to be airworthy.</i>  Steven F Barbieri AP 3129565 IA
				Pelican Aviation, Inc. Summerville SC 29483 10-01-10 N614DM Tach 570.5 TSN 570.5 Inspected prop for condition and security. No AD's apply at this time. Test ran OK at this time. <i>At the time of this inspection, I certify that this prop has been inspected in accordance with an ANNUAL inspection and was found to be airworthy.</i>  Steven F Barbieri AP 3129565 IA

Pelican Aviation, Inc. Summerville SC 29483

11-8-11 N614DM Tach 664.9 TSN 664.9

Inspected prop for condition and security. No AD's apply at this time. Test ran OK at this time.

At the time of this inspection, I certify that this prop has been inspected in accordance with an ANNUAL inspection and was found to be airworthy.

Steven F Barbieri

Steven F Barbieri AP 3129565 IA

11-12-12 771.6


INSPECTED PROPELLER USING FAR 43.0'h' as a GUIDE. NO DISCREPANCIES

noted, no AD's apply at this time. *John J Barbieri*
A01767223

Date 11-12-12 Total Time 771.6 Meter Time 771.6
I certify that this PROPELLER has been inspected in
accordance with ANNUAL inspection and was
determined to be in air worthy condition.

John J. Barbieri 1767223 IA

John J Barbieri

Date	Propeller TSN	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents Overhaul Major or Minor Repair and Inspections.																			
			580 Airport Road, Rock Hill, SC 29732 Phone: (803) 366-5108 / Fax: (803) 366-5230																			
			 Experience the Skytech Advantage																			
			<table border="1"> <tr> <td colspan="2">Propeller Log Entry</td> <td>Hobbs:</td> <td>772.7</td> <td>Registration #:</td> <td>N614DM</td> </tr> <tr> <td>Date:</td> <td>1 DEC 2012</td> <td></td> <td></td> <td>Make/Model:</td> <td>HC-I3YR-1RM</td> </tr> <tr> <td>W/O:</td> <td>UZA-100751</td> <td></td> <td></td> <td>S/N:</td> <td>HK1176B</td> </tr> </table>		Propeller Log Entry		Hobbs:	772.7	Registration #:	N614DM	Date:	1 DEC 2012			Make/Model:	HC-I3YR-1RM	W/O:	UZA-100751			S/N:	HK1176B
Propeller Log Entry		Hobbs:	772.7	Registration #:	N614DM																	
Date:	1 DEC 2012			Make/Model:	HC-I3YR-1RM																	
W/O:	UZA-100751			S/N:	HK1176B																	
			- Performed AD and SB research. No AD's due at this time. Reviewed 11/27/2012 - Performed ground run-up. NDN.																			
			MAINTENANCE RELEASE The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service with respect to work performed. Pertinent details of the repair are on file at this agency under <u>Work Order No:</u> <u>UZA-100751</u> Signed  for Skytech, Inc., PO Box 37507, Rock Hill, SC 29732. CRS# C41R727N																			
			1 of 1																			

PROP MODEL:
PROP S/N:
REG. NO: 614DM
WORK ORDER:
5818-11-2013



Premier Aircraft Service, Inc.
5540 NW 23rd Avenue Hanger 14
Fort Lauderdale, FL 33309
Phone: (954) 334-2393

DATE: 12/4/2013
A/C TSN: 960.4
PROP TT:
TACH: 960.4

Prop Entries

(6) REMOVED PROP AND REINSTALLED PROP AFTER OVERHAUL IAW PIPER MM CH 61-10-00 OPS AND LEAK CHECK GOOD... (7) C/W ANNUAL INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PA32R-301T MM CHAPTER 5 INSPECTION CHECKLIST AS A GUIDE. ADs CHECKED THROUGH CURRENT ON ATP.

I certify this propeller has been inspected in accordance with an ANNUAL inspection and found in airworthy condition on this date. Approved for return to service on this date.

DATE: 12/4/2013

SIGNED:

Sam Tavaraz, IA: 3521895

Work Order: 5818-11-2013

Printed by EBis 3 (datcomedia.com)

[illegible]

Date: 6/14/2015

Hours: 1175.0

Tail: N614DM

Make: Hartzell

Model: HC-I3YR-1RE

Serial: HK1176B

Comments:

C/W Annual Inspection on this propeller, lubed & filed & paint. I certify that this propeller has been inspected and found to be in airworthy condition. Checked all AD'S to date. -End -

Name: Alan Pakoyk

Cert: 1580072IA

Signature: 

[illegible]

7/27/17 HOBBS 1333⁹ T1 Prop 1333⁹

I CERTIFY THAT THIS PROP WAS INSPECTED IN ACCORDANCE WITH
A 100 HR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION
Mary Loose A82051687

PROP MODEL:
HC-13YR-1RF
PROP S/N: HK1176B
REG. NO: 614DM
WORK ORDER:
8989-07-2020



Premier Aircraft Service, Inc.
5540 NW 23rd Avenue Hanger 14
Fort Lauderdale, FL 33309
Phone: (954) 334-2393

DATE: 8/26/2020
A/C TSN: 1682.9
PROP TT: 1682.9
TSPOH: 0.1
HOBBS: 1682.9

Prop Entries

(4) C/W ANNUAL INSPECTION ON THIS PROPELLER IAW 14 CFR PART 43, APPENDIX "D" USING PA32R-301T MM INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED THROUGH CURRENT ON ATP.
(21) REMOVED AND RE INSTALLED PROPELLER P/N: HC-13YR-1RF S/N: HK1176B AFTER OVERHAUL FROM PALM BEACH AIRCRAFT PROP (UNDER W/O 21189) I.A.W. PA32R-301T MM CH 61-10-00.

I CERTIFY THIS AIRFRAME, ENGINE, OR PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

DATE: 8/26/2020

SIGNED:

Emmanuel Vicioso, IA: 3708718

Work Order: 8989-07-2020


Printed by EBis 3 (datcomedia.com)

DATE: Sept 13, 2022
MAKE / MODEL: Piper PA32R-301T
HM: 1,966.8



AIRCRAFT REG: N614DM
AIRCRAFT S/N: 3257434
AIRCRAFT TT: 1,966.8
TSMOH: 283.9

- PROPELLER MODEL: HC-13YR-1RF, SERIAL: HK1176B, TT: 1,966.8, TSMOH: 283.9
1. Filed the bade leading edges to remove minor nicks.
 2. I certify that this propeller has been inspected in accordance with a 100 hour inspection using Appendix D to FAR Part 43 as a guide and was determined to be in airworthy condition.


Signature  Thomas A Schmidt AP34856871A
Schmidt Aviation Inc. 1020 NW 62nd Street, Hangar 6, Ft Lauderdale, FL 33309


DATE: Nov 1, 2023
MAKE / MODEL: Piper PA32R-301T
HM: 2,024.9



AIRCRAFT REG: N614DM
AIRCRAFT S/N: 3257434
AIRCRAFT TT: 2,024.9
TSMOH: 342.0

- PROPELLER MODEL: HC-13YR-1RF, SERIAL: HK1176B, TT: 2,024.9, TSMOH: 342.0
1. Filed the bade leading edges to remove minor nicks.
 2. Sanded and painted the backs of the blades black.
 3. I certify that this propeller has been inspected in accordance with a 100 hour inspection using Appendix D to FAR Part 43 as a guide and was determined to be in airworthy condition.

Signature  Thomas A Schmidt AP34856871A
Schmidt Aviation Inc. 1020 NW 62nd Street, Hangar 6, Ft Lauderdale, FL 33309
(954) 772-0772, FAX (954) 938-5173, Email: Tom@Schmidtav.com



DATE: Feb 2, 2026

MAKE / MODEL: Piper PA32R-301T

HM: 2,086.6

AIRCRAFT REG: N614DM

AIRCRAFT S/N: 3257434

AIRCRAFT TT: 2,086.6

PROPELLER MODEL: HC-I3YR-1RF, SERIAL: HK1176B, TT: 2,086.6, TSMOH: 403.7

1. Filed the blade leading edges to remove minor nicks.
2. I certify that this propeller has been inspected in accordance with a 100 hour inspection using Appendix D to FAR Part 43 as a guide and was determined to be in airworthy condition.

Signature

Thomas A Schmidt AP34856871A

Schmidt Aviation Inc. 1020 NW 62nd Street, Hangar 6, Ft Lauderdale, FL 33309

(954) 772-0772, FAX (954) 938-5173, Email: Tom@Schmidtav.com