

LEFT ENGINE
SN 06752

17

AIRCRAFT TECHNICAL RECORD

Section 3. ENGINE LOG

Copyright - Austro Engine

Section 3A: Engine Service and Maintenance Log

DATE / /	TIME RUN		TIME SINCE OVERHAUL		CYCLES	
	HOURS	min	HOURS	min	Sub Total	TOTAL
BROUGHT						

DESCRIPTION OF WORK PERFORMED
(INSPECTION, REPAIRS, REPLACEMENT)

01757 (10-31-2025)

MAKE: DIAMOND AIRCRAFT INDUSTRIES
MODEL: DA-62
S/N: 62.247
REG. NO: N97PS
ENGINE MAKE - L: AUSTR0
ENGINE MODEL - L: E4PC
ENGINE SN - L: E4P-C-06752

400 Herdon Ave
Orlando , FL 32803


W/O #: 01757
DATE: 10-31-2025
A/C TT: 262.0
A/C Tach: 262.0
ENG TT - L: 0.0

MYFLIGHT

Entries

4 REMOVED LH ENGINE AND INSTALLED A NEW ENGINE IAW DIAMOND MM CHAPTER 71. REMOVED ENGINE S/N: E4P-C-06274 AND INSTALLED ENGINE S/N: E4P-C-06752.

I certify that this aircraft has been inspected for the work performed above and was determined to be in airworthy condition, and returned to service.

DATE: 10-31-2025
SIGNED: 
Matthew Hughes
A&P: 3705688 IA

WORK ORDER: 01757
Printed by EBIS (EBISCloud.com)

MAKE: Diamond
MODEL: DA62
S/N: 62.247
REG. NO: 97PS
MODEL-L: E4P
ENGINE S/N-L: E4P-C-06752




Premier Aircraft Service,
Inc.
CRS: # 9PRR402B
5540 NW 23rd Avenue Hangar 14
Fort Lauderdale, FL 33309

W/O #: 11366-02-2026
DATE: 04-03-2026
ENG TT - L: 50.8
Tach: 312.8

Left Engine Entries

3 C/W DA62 ANNUAL INSPECTION ON LEFT ENGINE IAW 14 CFR PART 43 APPENDIX D, USING DA62 CH 5 AND AUSTR0 E4.08.04 MM INSPECTION CHECKLIST AS A GUIDE. SERVICED ENGINE WITH 7 LITERS OF AEROSHELL DIESEL ULTRA 5W30 AND NEW ENGINE OIL FILTER P/N E4A-52-100-802. REPLACED FUEL FILTER WITH NEW P/N WK724_3 ENGINE WAS GROUND RUN AND LEAK CHECKED OK. AdS CHECKED THROUGH CURRENT ON ATP NAVIGATOR.
34 REPLACED LEFT ENGINE OIL DIPSTICK O-RING WITH NEW P/N OR_37.6X2.8-ACM70 IAW AUSTR0 E4.08.04 CH 79-10. LEAK CHECK GOOD.
35 REPLACED LEFT ENGINE OIL DRAIN PLUG WITH NEW P/N D44-9071-06-02 IAW E4.08.04 MM CH 79-00-00. LEAK CHECK GOOD.
40 REPLACED LEFT TURBOCHARGER ASSEMBLY WITH NEW PN: E4C-00-411-000 IAW AUSTR0 ENGINES E4 SERIES CH: 81-20.

I CERTIFY THIS AIRFRAME, ENGINE, OR PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

DATE: 04-03-2026
SIGNED: 
Dennis Allard
CRS: # 9PRR402B

WORK ORDER: 11366-02-2026
Printed by EBIS (EBISCloud.com)

MAKE: Diamond
MODEL: DA62
S/N: 62.247
REG. NO: 97PS
MODEL-L: E4P
ENGINE S/N-L: E4P-C-06752



Premier Aircraft Service,
Inc.
CRS: # 9PRR402B
5540 NW 23rd Avenue Hangar 14
Fort Lauderdale, FL 33309

W/O #: 11406-04-2026
DATE: 04-13-2026
ENG TT - L: 51.9
Tach: 313.7

Entries

2 REPLACED LH ENGINE OIL LEVEL SENSOR O-RING WITH NEW IAW AE300 MM CHAP 79-30-00. PERFORMED ENGINE GROUND RUN UP. NO OIL LEAKS NOTED.

DATE: 04-13-2026
SIGNED: 
Dennis Allard
CRS: # 9PRR402B

WORK ORDER: 11406-04-2026
Printed by EBIS (EBISCloud.com)

THIS PAGE TOTALS					
PREVIOUS TOTALS					
TOTALS SINCE NEW					

CARRY FORWARD to Top of Next Page

NAME/
SIGNATURELICENCE:
AME or
AMO/ACA

MAKE: Diamond
MODEL: DA62
S/N: 82.247
REG. NO: 97PS
MODEL-L: E4P
ENGINE S/N-L: E4P-C-
06752



**Premier Aircraft Service,
Inc.**
CRS: # 9PRR402B
5540 NW 23rd Avenue Hangar 14
Fort Lauderdale, FL 33309

W/O #: 11412-04-2026
DATE: 04-21-2026
ENG TT - L: 55.8
Tach: 317.4

Left Engine Entries

- 2 REPLACED LEFT ENGINE OIL LEVEL SENSOR WITH NEW UNIT P/N E4A-51-000-810 LOT RC2412291. IAW E4.08.04 MM CH 79-30-00 PERFORMED ENGINE GROUND RUN NO OIL LEAKS NOTED.

DATE: 04-21-2026

SIGNED:
Dennis Allard
CRS: # 9PRR402B

WORK ORDER: 11412-04-2026
Printed by EBIS (EBISCloud.com)

MAKE: Diamond
MODEL: DA62
S/N: 82.247
REG. NO: 97PS
MODEL-L: E4P
ENGINE S/N-L: E4P-C-
06752



**Premier Aircraft Service,
Inc.**
CRS: # 9PRR402B
5540 NW 23rd Avenue Hangar 14
Fort Lauderdale, FL 33309

W/O #: 11431-05-2026
DATE: 05-15-2026
ENG TT - L: 56.0
Tach: 318.0

Left Engine Entries

- 2 REPLACED OIL DRAIN VALVE WITH NEW P/N D44-9071-06-01. PERFORMED ENGINE GROUND RUN NO LEAKS NOTED IAW DA-62 MM. AND AE 300 MM CHAP 79-20-00.

DATE: 05-15-2026

SIGNED:
Dennis Allard
CRS: # 9PRR402B

WORK ORDER: 11431-05-2026
Printed by EBIS (EBISCloud.com)