

LEFT PROP

AIRCRAFT TECHNICAL RECORD

Section 4. PROPELLER LOG

PROPELLER LOG

1. Make MT-PROP
2. Model MTV-6-R-C-F/CF194-80
3. Specification Number _____
4. Date of Manufacture 2023
5. Hub Serial Number 230612
6. Blades
 - (a) Design No. _____
 - (b) Blade Serial Numbers:
 - (1) _____
 - (2) _____
 - (3) _____
 - (4) _____
 - (5) _____
 - (c) Pitch Settings
 - (1) Basic _____
 - (2) High _____
 - (3) Low _____
 - (4) Reverse _____



Section 4A: Propeller Service and Maintenance Record

DATE	TIME RUN	TOTAL TIME	
		SINCE OVERHAUL	
/ /	HOURS	MIN	MIN

DESCRIPTION OF WORK PERFORMED:
(INSPECTION, REPAIRS, REPLACEMENT)

01757 (11-08-2025)

Page 111

MYFLIGHT 

400 Haddon Ave
Orlando, FL 32803

W/O #: 01757
DATE: 11-08-2025
A/C TT: 262.0
A/C Tach: 262.0
Prop TT - L: 262.0

MAKE: DIAMOND AIRCRAFT
INDUSTRIES
MODEL: DA-62
S/N: 62-247
REG. NO: N87PS
PROP MAKE: - L: MT
PROP MODEL: - L: MTC6-R
C/F/C/F: 194-80
PROP 1 SN: 230612

Entries

- REMOVED AND REINSTALLED PROPELLER IAW DIAMOND MM CHAPTER 61-10.
 - REMOVED AND REPLACED PROPELLER GOVERNOR IAW DIAMOND MM CHAPTER 61. REMOVED PROP GOV SN: 23G18KG INSTALLED SN: 12G16S-HH
 - REMOVED AND REINSTALLED PROPELLER ACCUMULATOR IAW DIAMOND MM CHAPTER 61-20.
- I certify that this aircraft has been inspected for the work performed above and was determined to be in airworthy condition, and returned to service.

DATE: 11-08-2025

SIGNED:

Matthew Hughes
A&P: 3705688 JA

WORK ORDER: 01757
Printed by EBIS (EBIScloud.com)

MT-Propeller USA, Inc. 1180 Airport Terminal Drive, Deland, FL 32724

FAA Approved Repair Station Q4MR908Y

Phone: (386) 736-7762 Fax: (386) 736-7696 E-mail: info@mt-propellerusa.com

S/N: 230612

Propeller Model: MTV-6-R-C-F/C/F194-80

Propeller TSN: 262.0 Hts.

TDI of propeller in accordance with W/O# 25-642MT and Overhaul Manual E-220 Rev70.
Blade SN (1) ANK-96899 (2) ANK-96700 (3) ANK-96701

Year of Manufacture: 2023

I certify this propeller has been repaired and determined to be in airworthy condition at this time. Return to service this date, November 6, 2025

Peter Marshall, Chief Inspector Q4MR908Y 

MAKE: Diamond
MODEL: DA62
S/N: 62-247
REG. NO: 97PS
PROP MODEL: - L: MTV-6-
R-C-F/C/F194-80
PROP-1 SN: 230612

Premier
AIRCRAFT SERVICE

Inc.
CRS: # 9PRR402B
5540 NW 23rd Avenue Hangar 14
Fort Lauderdale, FL 33309

W/O #: 11386-02-2026
DATE: 04-03-2026
Prop TT - L: 312.8
Tach: 312.8

Left Propeller Entries

- CW ANNUAL INSPECTION ON LEFT PROPELLER IAW 14 CFR PART 43, APPENDIX 'D' USING MT-PROP-E-124 MM INSPECTION CHECKLIST AS A GUIDE. AOB CHECKED THROUGH CURRENT ON AIR.

I CERTIFY THIS AIRFRAME, ENGINE, OR PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

DATE: 04-03-2026

SIGNED:

Dennis Allard
CRS: # 9PRR402B

WORK ORDER: 11386-02-2026
Printed by EBIS (EBIScloud.com)

THIS PAGE TOTAL	
PREVIOUS TOTAL BROUGHT FORWARD	
TOTAL SINCE NEW	