AIRCRAFT
TECHNICAL RECORD

Section 1. AIRFRAME LOG

CALIBRATION CARD
ALTIMETER

P/N: 5934PD-3 C/N: A~~120~~250 S/N: 51978

Standard Alt (Ft)	Alt Reading (Ft) @ Room Temp	Standard Alt (Ft)	Alt Reading (Ft) @ Room Temp
-1,000	0	14,000	-15
0	+10	16,000	-10
500	+10	18,000	0
1,000	+5	20,000	+25
1,500	0	22,000	[redacted]
2,000	0	25,000	
3,000	0	30,000	
4,000	0	35,000	
6,000	-10	40,000	
8,000	-15	45,000	
10,000	-20	50,000	
12,000	-15		

Date: NOV 25/20 Tested By: [redacted] Inspected By: DA Q 112

Diamond Aircraft Industries
Reference QP-05-08-113

ations MMX

AIRCRAFT

1. Nationality and Registration:	N123NG
2. Manufacturer's designation:	DA 40 NG
3. Manufacturer's Serial Number:	40.NC123
4. Type Approval or Specification Number:	A47CE
5. Date of Manufacture:	2020
6. Aircraft Inspections cycle:	

Diamond AIRCRAFT

DIAMOND AIRCRAFT INDUSTRIES INC.
D.O.T. APPROVED MANUFACTURER #161-93

Registration:	N123NG
AC Serial Number:	40.NC123
Engine Serial Number:	E4-A-06023
Prop Serial Number:	201471
Airframe Total Time:	3.4 HRS

- Total Time **Airframe** Brought forward from Flight Test Journey Log (DAI - Form Q-157): 3.4 HRS
- Compass Swing Performed:
  - Date: 08 JANUARY 2021
  - Next Due: JANUARY 2022

FOR	N	30	60	E	120	150
STEER	360	030	058	091	121	152
FOR	S	210	240	W	300	330
STEER	178	212	238	270	301	333

- Static Pressure system and Primary Altimeter (G1000) have been inspected and tested in accordance with CAR Standard 571, Appendix B and 14 CFR 91.411:
  - Test Date: 11 DECEMBER 2020
  - Next Due: DECEMBER 2022
- Standby Altimeter:
  - Factory Test Date: NOVEMBER 25 2020
  - Next Due: NOVEMBER 2022
- ATC Transponder & Altitude Reporting System(s) have been tested in Accordance with CAR Standard 571, Appendix F and 14 CFR 91.217: & 91.413:
  - Test Date: 11 DECEMBER 2020
  - Next Due: DECEMBER 2022
  - Programmed Registration: N123NG
  - Hex Code: N/A (U.S. Registration)
- The ELT was tested and inspected in Accordance with CAR Standard 571, Appendix G and 14 CFR 91.207(d) :
  - Manufacturers Cert. date: 42/20
  - Installation Inspected: 08 JANUARY 2021
  - Battery due: SEPTEMBER 2027
  - Next ELT inspection due: JANUARY 08 2022
  - ELT Programmed:
    - REG: N123NG
    - HEX: N/A
    - Country: 366 (USA)
    - Beacon ID: ADC6499D650E6B1
- Emergency Battery Pack : Replacement Due Date : NOVEMBER 2022
- Garmin G1000 NXi Installation:
  - Software System: 2948.11
  - Checklist File: N/A
  - Basemap Land 5.18
  - SafeTaxi Data: 25-FEB-2021
  - Terrain Data: 3.00
  - Obstacle Data: Expires 25-FEB-2021
  - Navigation Data: Expires 28-JAN-2021
  - Apt Directory: Expires 25-FEB-2021
  - FliteCharts Data: Expires 28-JAN-2021
  - IFR/VFR charts: Date: 31-DEC-2020

DA Q 8

Inspector

JAN 1 1 2021

Date

(continued next page)

Diamond AIRCRAFT

DIAMOND AIRCRAFT INDUSTRIES INC.
D.O.T. APPROVED MANUFACTURER #161-93

Registration:	N123NG
AC Serial Number:	40.NC123NG
Engine Serial Number:	E4-A-06023
Prop Serial Number:	201471
Airframe Total Time:	3.4 HRS

- Following limitations as per DA 40 AMM Chapter 4 (subject to change with revision):

Component	Hours	Years	Next Due:
Essential Bus	1000	-N/A-	1000 hrs
Pitot-Static System	1000	2	1000 hrs or DEC 2022
Bonding System	1000	-N/A-	1000 hrs
Emergency Battery Pack	-N/A-	2	NOVEMBER 2022
ECU Backup Battery	-N/A-	1	NOVEMBER 2021

- The following STC's are incorporated:
  - No STC's incorporated.

- THIS AIRCRAFT WAS INSPECTED FOR CONFORMITY TO APPLICABLE COMPANY RELEASED DOCUMENTS (DRAWINGS, SPECIFICATIONS, CONCESSIONS).
- I HEREBY CERTIFY THAT THIS AIRCRAFT CONFORMS TO FAA TYPE CERTIFICATE A47CE Rev No. 16, AND IS IN A FIT AND SAFE STATE FOR FLIGHT.
- **Bi-weekly AWD check carried out to current revision 2021-01 all applicable AD's complied with, see attached.**
- The work described above was carried out IAW the applicable Standard of Airworthiness.

DA Q 8
Inspector

JAN 1 1 2021
Date

(Intentionally left blank below this point)

U.S. Standard Airworthiness Certificate, issued:

(Date) JAN 1 5 2021 **, has been installed in the Aircraft on behalf of FAA Farmingdale/Saddle Brook MIDO Section AIR-8A5 on:**

(Date) JAN 1 5 2021

(Print) L. Berrios **(Signature)**

DEPARTMENT OF TRANSPORT MINISTÈRE DES TRANSPORTS
Délégué de l'Aviation civile
Canada
0382
Civil Aviation Delegate

Section 1: Airframe Log

DATE / /	AIR TIME				LANDINGS / CYCLES		DETAILS OF TASK (INSPECTION, REPAIRS & REPLACEMENT)
	DAILY TOTAL		TOTAL		DAILY TOTAL	TOTAL	
	HRS	MIN	HOURS	MIN			
CARRIED FORWARD							

MAKE: Diamond
MODEL: DA-40NG
S/N: 40.NC123
REG. NO: 123NG
WORK ORDER: 9353-04-2021

Premier Aircraft Service

Premier Aircraft Service,. Inc.
5540 NW 23rd Avenue Hanger 14
Fort Lauderdale, FL 33309
Phone: (954) 334-2393

DATE: 5/11/2021
A/C TSN: 64.1
TACH: 64.1

Airframe Entries

(3) REPLACED KEYPAD CONTROLLER WITH NEW P/N DAI-9021-00-03_1 S/N 2102 00619 02 AND SERVICED AIR CONDITIONING SYSTEM IAW DA40NG MM CH 21-50-00. OPS CHECKED GOOD.
(5) PAINTED NOSE WHEEL FAIRING IAW DA40 NG MM CH 51-20.

DATE: 5/11/2021 SIGNED:

SAMUEL TAVAREZ JR.
CRS# 9PRR402B

Work Order: 9353-04-2021

Printed by EBis 3 (datcomedia.com)

MAKE: Diamond
MODEL: DA-40NG
S/N: 40.NC123
REG. NO: 123NG
WORK ORDER: 9582-11-2021

Premier Aircraft Service

Premier Aircraft Service,. Inc.
5540 NW 23rd Avenue Hanger 14
Fort Lauderdale, FL 33309
Phone: (954) 334-2393

DATE: 11/9/2021
A/C TSN: 180.4
TACH: 180.4

Airframe Entries

(7) C/W AD 2016-23-03 TURBO V-CLAMP INSPECTION. NO DEFECTS NOTED AT THIS TIME.
(12) TIRES SERVICED IAW DA40NG MM CH 12-00.

DATE: 11/9/2021 SIGNED:

EMMANUEL VICIOSO
CRS 9PRR402B

Work Order: 9582-11-2021

Printed by EBis 3 (datcomedia.com)

Make: Diamond
Model: DA40NG
S/N:40.NC123
REG NO: N123NG

Diamond FLEET & AVIATION SERVICES

Diamond Fleet & Aviation services LLC
5070 S. Collins suite 205,
Arlington, TX 76018
Phone: 817-575-7828

Date: 12/13/2021
Hobbs: 244.6
A/C TSN: 195.0

Airframe entry:

- Performed 100 hour/Annual inspection using DA40NG AMM as a guide
- Performed 200 hour inspection
- Complied with 100 hour lubrication
- Inspected ELT system IAW 14 CFR 91.207
- Replaced fuel filter
- Replaced two backup ECU batteries with new ones P/N: NP7-12
- Replaced two Air conditioner batteries P/N: NP1.2-12
- Replaced Two rudder nuts with new ones P/N: DIN985-M6-A2
- Replaced K&N High flow air filter with new one P/N: RU-1620
- All AD's complied with current Bi-week

I certify this aircraft has been inspected IAW a 100 hour/Annual inspection and was determined to be in an airworthy condition.

Date: 12/13/2021 SIGNED:

FA 3397718

PAGE TOTALS							CARRY FORWARD to Top of Next Page

MAKE: Diamond
MODEL: DA40NG
S/N: 40.NC123
REG. NO: N123NG
WORK ORDER: 0498

Premier Aircraft Service

Premier Aircraft Service, Inc.
3804 Falcon Way W
Hangar 18S
Fort Worth, TX 76106
Phone: 562.881.5345

DATE: 12/21/2021
A/C TSN: 195.3
HOBBS: 246.1

Airframe Entries

- Replaced diode at 2nd alternator relay

DATE: 12/21/2021 SIGNED:

David Seastead, License: AP3492477 IA

Work Order: 0498

Printed by EBis 3 (datcomedia.com)

MAKE: Diamond
MODEL: DA40NG
S/N: 40.NC123
REG. NO: N123NG
WORK ORDER: 0525

Premier Aircraft Service

Premier Aircraft Service, Inc.
3804 Falcon Way W
Hangar 18S
Fort Worth, TX 76106
Phone: 562.881.5345

DATE: 2/15/2022
A/C TSN: 248.8
HOBBS: 318.7

Airframe Entries

- Replaced com2 antenna with new S/N 27672

DATE: 2/15/2022 SIGNED:

David Seastead, License: AP3492477 IA

Work Order: 0525

Printed by EBis 3 (datcomedia.com)

wo: N123NG 2022.04.01 Scheduled

Airframe - page 1 of 1

Diamond FLEET & AVIATION SERVICES

Diamond Fleet & Aviation Service - 5070 S. Collins S. Suite 205 - Arlington, TX 76018 - 9012474808

N123NG **DIAMOND AIRCRAFT IND INC, DA 40 NG, S/N: 40.NC123** **April 04, 2022**
HOBBS: 372.1 TACH: 288.6

1. **100 Hour Inspection - Airframe** – 100 Hour Inspection completed in IAW FAR 43 Appendix D, DAI DA40NG AMM (CH4 Airworthiness Limitations & CH5 MX Schedules) as a guide. Rotated MLG tires for wear evenness. FAR 91.207 ELT Inspection Completed. 100 Hour Lubrication Requirements Completed. All ADs complied with through current bi-week.
2. **Magnetometer access panel has 1ea Rivnut stripped.** – Removed Rivnut and replaced with new-serviceable rivnut.

With respect to the work performed, this aircraft has been found to be in an airworthy condition and is approved for return to service. Details of work performed are on file with Diamond Fleet & Aviation Service under work order: N123NG 2022.04.01 Scheduled.

Michael Smith A/P 3906663

wo: N123NG 2022.06.28 Scheduled

Airframe · page 1 of 1

Diamond FLEET & AVIATION SERVICES

Diamond Fleet & Aviation Services · 5070 S. Collins S. Suite 205 · Arlington, TX 76018 · 9012474808

N123NG
HOBBS: 521.9

DIAMOND AIRCRAFT IND INC, DA 40 NG, S/N: 40.NC123
TACH: 393.7

July 01, 2022

1. **100 Hour Inspection** – Inspection completed using DA40NG AMM current revision as a guide. 100 hour airframe lubrication completed. All ADs complied with through current bi-week. Next due @ 493.3 TACH.
2. **100 Hour/12 Month Fuel Filter Replacement** – Removed fuel filter (P/N: WK724_3) and replaced with new-serviceable fuel filter (P/N: WK724_3) IAW DA40NG AMM. Next due @ 493.3 TACH or 31 July 2023.
3. **100 Hour/12 Month ELT Operational Check (14 CFR Part 91.207)** – Inspected IAW FAR 91.207 - battery expires Jan2027. Next inspection due 493.3 TACH or 31 July 2023.
4. **7 Day Weekly Wipedown** – IAW Company Policy.
5. **L/H MLG Tire Worn** – Removed L/H MLG Tire (p/n 301-249-006 s/n unk) and tube (p/n 097-500-00) and installed new-serviceable tire (p/n same s/n: 20190706) and new-serviceable tube (p/n same) IAW DA40NG AMM and Cleveland Wheel ICA current revisions.
6. **R/H MLG Tire Worn** – Removed L/H MLG Tire (p/n 301-249-006 s/n unk) and tube (p/n 097-500-00) and installed new-serviceable tire (p/n same s/n: 20200273) and new-serviceable tube (p/n same) IAW DA40NG AMM and Cleveland Wheel ICA current revisions.
7. **12 Month Compass Compensation** – Completed IAW DA40NG AMM current revision. Updated deviation card in aircraft. Next due 31July2023.

With respect to the work performed, this aircraft has been found to be in an airworthy condition and is approved for return to service. Details of work performed are on file with Diamond Fleet & Aviation Services under work order: N123NG 2022.06.28 Scheduled.

Caleb Rendon A/P 4231209 _____

wo: N123NG 2022.07.15 Unscheduled

Airframe · page 1 of 1

Diamond FLEET & AVIATION SERVICES

Diamond Fleet & Aviation Services · 5070 S. Collins S. Suite 205 · Arlington, TX 76018 · 9012474808

N123NG
HOBBS: 549.2

DIAMOND AIRCRAFT IND INC, DA 40 NG, S/N: 40.NC123
TACH: 411.8

July 15, 2022

1. **RACC Intermittent** – Removed RACC alternator brush block assembly and installed new-serviceable brush block assembly IAW DA40NG AMM & Hartzell Aero ICA.

With respect to the work performed, this aircraft has been found to be in an airworthy condition and is approved for return to service. Details of work performed are on file with Diamond Fleet & Aviation Services under work order: N123NG 2022.07.15 Unscheduled.

Michael Smith A/P 3906663 _____

N123NG HOBBS: 550.9 TACH: 413.2 DA-40 NG S/N: 40.NC123 July 23, 2022

RACC Inoperative - alternator brush block has been replaced & R134a refrigerant charge has been verified

– Reeves Kunakasie, 3389632CFI

MAKE: Diamond
MODEL: DA40NG
S/N: 40.NC123
REG. NO: N123NG
WORK ORDER: 0664

Premier Aircraft Service

Premier Aircraft Service, Inc.
3804 Falcon Way W
Hangar 18S
Fort Worth, TX 76106
Phone: 562.881.5345

DATE: 9/16/2022
A/C TSN: 454.7
HOBBS: 601.9

Airframe Entries

- Replaced brake linings

DATE: 9/16/2022 SIGNED: _____

Chad Cox, License: AP3782800 IA

Work Order: 0664

Printed by EBis 3 (datcomedia.com)

NAME/ SIGNATURE	LICENCE: AME or AMO/ACA

MAKE: Diamond
MODEL: DA40NG
S/N: 40.NC123
REG. NO: N123NG
WORK ORDER: 0637

Premier Aircraft Service, Inc.
3804 Falcon Way W
Hangar 18S
Fort Worth, TX 76106
Phone: 562.881.5345

DATE: 9/16/2022
A/C TSN: 454.7
HOBBS: 601.9

Airframe Entries

- Replaced 2nd alternator with new assembly D64-2416-30-00_01ASY (ES-10024B-2 S/N H-W041917)

DATE: 9/16/2022 SIGNED:

Chad Cox, License: AP3782800 IA

Work Order: 0637

Printed by EBis 3 (datcomedia.com)

MAKE: Diamond
MODEL: DA40NG
S/N: 40.NC123
REG. NO: N123NG
WORK ORDER: 0726

Premier Aircraft Service, Inc.
3804 Falcon Way W
Hangar 18S
Fort Worth, TX 76106
Phone: 562.881.5345

DATE: 12/12/2022
A/C TSN: 536
HOBBS: 701.8

Airframe Entries

- Performed Annual Inspection using DA40NG AMM as a guide
- Inspected ELT system IAW 14 CFR 91.207(d)
- Replaced ECU backup batteries
- Replaced fuel filter
- Complied with 100 Hour lubrication
- Performed autopilot mechanical check
- Performed RACC leak check and serviced system with freon and oil
- Performed main battery capacitance check, passed at 102%
- Replaced induction air filter
- Replaced emergency battery
- Installed battery minder airframe interface kit BM-AIK2A
- Installed fuel filter splash guard

I certify this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

DATE: 12/12/2022 SIGNED:

Chad Cox, License: AP3782800 IA

Work Order: 0726

Printed by EBis 3 (datcomedia.com)

PDG Services + 670 Ferris Rd., Ste. 104 + Lancaster, TX. 75146

ACFT REG. N123NG HOBBS TIME 701.0

The ~~STBY~~ altimeter system has been inspected and found to comply with the requirements of FAR part 91.411, to an altitude of 20,000 ft. Pertinent details of the certification are on file at this repair station under the work order # 22-1203 , dated 12-6-22

Paul Gardner (Authorized Signature) 12-6-22
CRS G49R038Y 214-886-5894 (Date)

PDG Services + 670 Ferris Rd., Suite 104 + Lancaster TX 75146

ACFT REG. N123NG HOBBS TIME 701.0

The ALT altimeter, transponder & altitiude reporting system has been inspected and found to comply with the requirements of FAR 91.411 & 91.413, to an altitude of 20 ,000 ft. Pertinent details of the certification are on file at this repair station under the work order # 22-1203 , dated 12-6-22.

Paul Gardner (Authorized Signature) 12-6-22
CRS G49R038Y 214-886-5894 (Date)

Section 1: Airframe Log

DATE / /	AIR TIME				LANDINGS / CYCLES		DETAILS OF TASK (INSPECTION, REPAIRS & REPLACEMENT)
	DAILY TOTAL		TOTAL		DAILY TOTAL	TOTAL	
	HRS	MIN	HOURS	MIN			
CARRIED FORWARD ▶							

MAKE: Diamond
MODEL: DA40NG
S/N: 40.NC123
REG. NO: N123NG
WORK ORDER: 0856

Premier Aircraft Service, Inc.
3804 Falcon Way W
Hangar 18S
Fort Worth, TX 76106
Phone: 562.881.5345

DATE: 5/31/2023
A/C TSN: 585.1
HOBBS: 765

Airframe Entries

- Replaced NLG wheel pant with new assembly D41-3223-91-00_1-SET

DATE: 5/31/2023 SIGNED:
David Seastead, License: AP3492477 IA

Work Order: 0856
Printed by EBis 3 (datcomedia.com)

MAKE: Diamond
MODEL: DA40NG
S/N: 40.NC123
REG. NO: N123NG
WORK ORDER: 0869

Premier Aircraft Service, Inc.
3804 Falcon Way W
Hangar 18S
Fort Worth, TX 76106
Phone: 562.881.5345

DATE: 6/27/2023
A/C TSN: 597.1
HOBBS: 779.8

Airframe Entries

- Replaced main battery with new RG24-15 S/N 41194339

DATE: 6/27/2023 SIGNED:
David Seastead, License: AP3492477 IA

Work Order: 0869
Printed by EBis 3 (datcomedia.com)

MAKE: Diamond
MODEL: DA40NG
S/N: 40.NC123
REG. NO: N123NG
WORK ORDER: 0878

Premier Aircraft Service, Inc.
3804 Falcon Way W
Hangar 18S
Fort Worth, TX 76106
Phone: 562.881.5345

DATE: 10/11/2023
A/C TSN: 634.1
HOBBS: 823.9

Airframe Entries

- Replaced RACC control panel DAI-9021-00-03_1
- Replaced 2nd alternator brush pack ALU-3045BS

DATE: 10/11/2023 SIGNED:
David Seastead, License: AP3492477 IA

Work Order: 0878
Printed by EBis 3 (datcomedia.com)

MAKE: Diamond
MODEL: DA40NG
S/N: 40.NC123
REG. NO: N123NG
WORK ORDER: 1016

Premier Aircraft Service, Inc.
3804 Falcon Way W
Hangar 18S
Fort Worth, TX 76106
Phone: 562.881.5345

DATE: 1/2/2024
A/C TSN: 637.1
HOBBS: 828.1

Airframe Entries

- Performed Annual Inspection using DA40NG AMM as a guide
- Inspected ELT system IAW 14 CFR 91.207(d)
- Replaced ECU backup batteries
- Complied with 100 Hour lubrication

I certify this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

DATE: 1/2/2024 SIGNED:
David Seastead, License: AP3492477 IA

Work Order: 1016
Printed by EBis 3 (datcomedia.com)

PAGE TOTALS ▶ CARRY FORWARD to Top of Next Page ▶

PDG Services, 670 Ferris Rd. Ste. 104, Lancaster, TX, 75146

ACFT REG: N123NG Hobbs TIME: 930.0

The #1 altimeter, transponder & altitude reporting systems has been tested and found to comply with the requirements of FAR 91.411 & 91.413 to an **altitude of** 20 **,000 ft.** Pertinent details of the certification are on file at this repair station under the **work order #** 25-0102 **, dated** 1.13.25

Paul Gardner — *(Authorized Signature)* — 1.13.25 *(Date)*
CRS G49R038Y — 214-886-5894

PDG Services, 670 Ferris Rd. Ste. 104, Lancaster, TX, 75146

ACFT REG: N123NG Hobbs TIME: 930.0

The #1 altimeter system has been tested and found to comply with the requirements of FAR 91.411 to an **altitude of** 20 **,000 ft.** Pertinent details of the certification are on file at this repair station under the **work order #** 25-0102 **, dated** 1.13.25

Paul Gardner — *(Authorized Signature)* — 1.13.25 *(Date)*
CRS G49R038Y — 214-886-5894

NAME/ SIGNATURE | LICENCE: AME or AMO/ACA

MAKE: Diamond
MODEL: DA40NG
S/N: 40.NC123
REG. NO: N123NG

Premier Aircraft Service, Inc.
3804 Falcon Way W
Hangar 18S
Fort Worth TX 76106

W/O #: 1293
DATE: 02-10-2025
Airframe TT: 724.5
Tach: 724.5
Hobbs: 930.8

Airframe Entries

- Performed Annual Inspection using DA40NG AMM as a guide
  Inspected ELT system IAW 14 CFR 91.207(d)
  Replaced ECU backup batteries
  Replaced fuel filter
  Complied with 100 Hour lubrication
- Replaced emergency battery with new case D60-2560-92-00 and CR123A batteries
- Performed brake fluid flush
- Replaced induction air filter RU-1620
- Replaced RH inboard fuel tank D4D-2817-22-00
- Replaced RH wing seal DAI-9057-00-01
- Replaced main tires 156E66-4 and tubes GL-1520B
  Replaced nose tire 505C61-8 and tube GL-5067B

I certify this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

DATE: 02-10-2025 SIGNED:

David Seastead
License: AP3492477 IA

WORK ORDER: 1293

Printed by EBIS (EBISCloud.com)

Section 1: Airframe Log

MAKE: Diamond
MODEL: DA40NG
S/N: 40.NC123
REG. NO: N123NG

Premier Aircraft Services
3804 Falcon Way W
Hangar 18S
Fort Worth TX 76106

W/O #: 1706
DATE: 03-09-2026
Airframe TT: 752.2
Tach: 752.2
Hobbs: 930.8

Airframe Entries

Performed Annual Inspection using DA40NG AMM as a guide
Inspected ELT system IAW 14 CFR 91.207(d)
Replaced ECU backup batteries
Replaced fuel filter
Complied with 100 Hour lubrication
AD 2016-23-03 Inspected turbo clamp IAW MSB40NG-046/2
Replaced 2nd alternator with new D64-2416-30-00_01ASY S/N H-Z101085
Replaced exhaust pipe with new D44-7806-20-00_02

I certify this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

DATE: 03-09-2026 SIGNED:

Chad Cox
License: AP3782800 IA

WORK ORDER: 1706
Printed by EBIS (EBISCloud.com)

PAGE TOTALS

CARRY FORWARD to Top of Next Page