

AIRCRAFT TECHNICAL RECORD

Section 3. ENGINE LOG

ENGINE LOG

- | | |
|----------------------------------|---------------------|
| 1. Make: | Austro Engines GmbH |
| 2. Model: | E4-A |
| 3. Specification: | E00081EN |
| 4. Manufacturer's Serial Number: | E4-A-06577 |
| 5. Date of Manufacture: | JUNE 14 2023 |
| 6. Aircraft Inspection Cycle: | |



Section 3A: Engine Service and Maintenance Log

DATE / /	TIME RUN		TIME SINCE OVERHAUL		CYCLES		DESCRIPTION OF WORK PERFORMED (INSPECTION, REPAIRS, REPLACEMENT)
	HOURS	min	HOURS	min	Sub Total	TOTAL	
BROUGHT FORWARD							



DIAMOND AIRCRAFT INDUSTRIES INC.
D.O.T. APPROVED MANUFACTURER #161-93

Registration: N627PS
AC Serial Number: 40 NC257
Engine Serial Number: E4-A-06577
Prop Serial Number: 231261
Airframe Total Time: 3.2 HRS

- Total Time Engine Brought forward from Flight Test Journey Log (DAI - Form Q-157): 3.2 HRS
- Engine installed new on Aircraft DA 40 NG, S/N: 40 NC257
- Bi-weekly AWD check carried out to current revision 2023-16 all applicable AD's complied with, see attached.
- The work described above was carried out in accordance with the applicable Standard of Airworthiness.

[Signature]
DA
Q 8
Inspector

AUG 02 2023

Date

(Intentionally left blank below this point)

ENGINE MODEL AE300
ENGINE S/N E4-A-06577
REG NO N627PS
WORK ORDER 0984



Premier Aircraft Service, Inc.

3804 Falcon Way W
Hangar 18S
Fort Worth, TX 76105
Phone 562 881 5345

DATE 4/4/2024
A/C TSN 889
ENG TT 889
HOBBS 116.4

Engine Entries

- AD 2024-05-01 Replaced main bearing cap bolts E4A-10-100-202 IAW MSB-E4-042/1

DATE 4/4/2024

SIGNED:

[Signature]

Chad Cox, License AP3782800 IA

Work Order: 0984

Printed by EBIS 3 (datcomedia.com)

9-1-2024	HOBBS 126.1	TTCN 95.4	INSPECT & SERVICE
LOW SERVICE MANUAL. CHANGED OIL & FILTER. RESERVES			
WITH 6 QTS ARROWELL DIESEL ULTRA. REPLACE			
FUEL FILTER. RUN UP SATISFACTORY AND LEAK CHECK.			
THIS ENGINE HAS BEEN INSPECTED IAW A100 HR			
INSPECTION & FOUND AIRWORTHY. SHOWN & PASSED			

ENGINE MODEL AE300
ENGINE S/N E4-A-06577
REG NO N627PS
WORK ORDER 1218



Premier Aircraft Service, Inc.

3804 Falcon Way W
Hangar 18S
Fort Worth, TX 76106
Phone 562 881 5345

DATE 9/26/2024
A/C TSN 98.5
ENG TT 98.5
HOBBS 128.9

Engine Entries

- AD 2024-19-10 Inspected pistons IAW MSB-E4-043

DATE 9/26/2024

SIGNED:

[Signature]


Chad Cox, License AP3782800 IA

Work Order: 1218

Printed by EBIS 3 (datcomedia.com)

SINCE NEW

CARRY FORWARD to Top of Next Page



Take Flight Aviation LLC · 49 Hangar Road · Montgomery, NY 12549 · 8454574188

N627PS

Hobbs: 151.3

Austro, E4A, S/N: E4-A-06577

TACH: 117.1

December 20, 2024

1. Performed 100hr engine inspection using Austro Engines E4 Manual and Diamond AMM checklist for reference. Installed (7) P/N 5W30LT - Aeroshell, Installed P/N HU615/3x - Oil filter, Installed P/N Blackstone Kit - Oil Analysis.
2. Drained oil, retained sample for analysis. Removed filter, inspected with no contamination noted. Installed new filter, safety wired and added 7qts Aeroshell Ultra Diesel oil.
3. All routine service items performed. Installed (1 gal) P/N SPIRAX-S6-GXME75W - Gearbox Oil, Installed P/N Zerex-G48 - Zerex G48.
4. Inspected engine coolant tank and pressure checked as required.
5. Visually inspected turbo charger and lubricated as required.
6. Inspected exhaust system as required.
7. Examined all belts and wiring with no defect noted.
8. All applicable ADs checked bi-weekly thru this date.
9. Serviced coolant to proper level as required.
10. Removed and replaced turbo with new as required. Installed P/N E4A-00-410-BHY - Turbo E4A with waste gate controller, Installed P/N E4A-04-000-003 - Exhaust Gasket Rev/Lot: RC2107518, Installed P/N E4A-01-000-401 - Gasket.
11. Compiled with AD2024-19-10 by boroscope of engine pistons IAW MSB 043. No cracks noted. Next due Tach: 167.1 Installed P/N MSB-E4-043-KIT - MSB-E4-043-KIT.

I certify that this engine has been inspected in accordance with a 100hr Inspection at Take Flight Aviation, LLC., and that this engine has been determined airworthy and approved for return to service.

James T. Markey A&P 3166872

Engine - page 1 of 1



Take Flight Aviation LLC · 49 Hangar Road · Montgomery, NY 12549 · 8454574188

N627PS

Hobbs: 224.6

AUSTRO, E4-A, S/N: E4-A-06577

Tach: 166.1

January 14, 2025

Complied with AD2024-19-10 Piston boroscope by boroscope inspection IAW MSBE4-043 with no cracks noted. Next due Tach: 216.1 Installed P/N MSB-E4-043-KIT - MSB-E4-043-KIT.

Run up and functional check of work completed satisfactory

James T. Markey A&P 3166872

Engine - page 1 of 1



Take Flight Aviation LLC · 49 Hangar Road · Montgomery, NY 12549 · 8454574188

N627PS

Hobbs: 261.5

Diamond, DA40NG, S/N: 40.NC257

Tach: 117.1

January 24, 2025

Removed and replaced glow plug controller with serviceable unit. Removed S/N: 005445 Installed S/N: 002189. Installed P/N E4A-94-200-000-043 - Glow plug controller.


Functional check of work completed satisfactory.

James T. Markey A&P 3166872

Section 3A: Engine Service and Maintenance Log

DATE / /	TIME RUN		TIME SINCE OVERHAUL		CYCLES		DESCRIPTION OF WORK PERFORMED (INSPECTION, REPAIRS, REPLACEMENT)
	HOURS	min	HOURS	min	Sub Total	TOTAL	
BROUGHT FORWARD							

Engine page 1 of 1



Take Flight Aviation LLC · 49 Hangar Road · Montgomery, NY 12549 · 8454574188

N627PS

Hobbs: 297.6

Tach: 213.7


Diamond, DA40NG, S/N: 40-NC257 **AUSTO SNE4-A-06577** **February 03, 2025**

1. Performed 100hr engine inspection using Austro Engines E4 Manual and Diamond AMM checklist for reference. Installed (7) P/N 5W30LT - Aeroshell, Installed P/N HU615/3x - Oil filter.
2. Drained oil, retained sample for analysis. Removed filter, inspected with no contamination noted. Installed new filter, safety wired and added 7qts Aeroshell Ultra Diesel oil. Installed P/N Blackstone Kit - Oil Analysis.
3. All routine service items performed.
4. Inspected engine coolant tank and pressure checked as required.
5. Visually inspected turbo charger and lubricated as required.
6. Inspected exhaust system as required.
7. Examined all belts and wiring with no defect noted.
8. All applicable ADs checked bi-weekly thru this date.
9. Complied with AD2024-19-10 Piston boroscope by boroscope inspection IAW MSBE4-043 with no cracks noted. Next due Tach: 213.7 263.7

I certify that this engine has been inspected in accordance with a 100hr Inspection and that this engine is approved for return to service.

Bryce Hetherly A&P 3959164

Engine page 1 of 1



Take Flight Aviation LLC · 49 Hangar Road · Montgomery, NY 12549 · 8454574188

N627PS

Hobbs: 436.9

Tach: 306.2

Austro, E4-A, S/N: E4-A-06577

March 07, 2025

1. Performed 100hr engine inspection using Austro Engines E4 Manual and Diamond AMM checklist for reference. Installed (7) P/N 5W30LT - Aeroshell, Installed P/N HU615/3x - Oil filter.
2. Drained oil, retained sample for analysis. Removed filter, inspected with no contamination noted. Installed new filter, safety wired and added 7qts Aeroshell Ultra Diesel oil. Installed P/N Blackstone Kit - Oil Analysis.
3. All routine service items performed. Installed (2 gal) P/N SPIRAX-S6-GXME75W - Gearbox Oil.
4. Inspected engine coolant tank and pressure checked as required.
5. Visually inspected turbo charger and lubricated as required.
6. Inspected exhaust system as required.
7. Examined all belts and wiring with no defect noted.
8. All applicable ADs checked bi-weekly thru this date.
9. Complied with AD2024-19-10 Piston boroscope by boroscope inspection IAW MSB-E4-043 with no cracks noted. Next due Tach: 356.2 Installed P/N MSB-E4-043-KIT - MSB-E4-043-KIT.

I certify that this engine has been inspected in accordance with a 100hr Inspection and approved for return to service.

Bryce Hetherly A&P 3959164

THIS PAGE TOTALS									
PREVIOUS TOTALS									
TOTALS SINCE NEW									

CARRY FORWARD to Top of Next Page



Take Flight Aviation LLC · 49 Hangar Road · Montgomery, NY 12549 · 8454574188

N627PS

Hobbs: 372.5

AUSTRO, E4-A, S/N: E4-A-06577

Tach: 263.1

February 21, 2025

Out of Sequence

Complied with AD2024-19-10 Piston boroscope by boroscope inspection IAW MSBE4-043 with no cracks noted. Next due Tach: 313.1 Installed P/N MSB-E4-043-KIT - MSB-E4-043-KIT.

Run up and leak check satisfactory

James T. Markey A&P 3166872

James T. Markey



Take Flight Aviation LLC · 49 Hangar Road · Montgomery, NY 12549 · 8454574188

N627PS

Hobbs : 510.2

AUSTRO, E4-A, S/N: E4-A-06577

Tach: 356.5

March 28, 2025

Complied with AD2024-19-10 Piston boroscope by boroscope inspection IAW MSBE4-043 with no cracks noted. Next due Tach: 456.5 Installed P/N MSB-E4-043-KIT - MSB-E4-043-KIT.

Run up and functional check of work completed satisfactory

James T. Markey A&P 3166872

James T. Markey



Take Flight Aviation LLC · 49 Hangar Road · Montgomery, NY 12549 · 8454574188

N627PS

Hobbs: 581.3

Austro, E4-A, S/N: E4-A-06577

Tach: 404.9

April 24, 2025

1. Performed 100hr engine inspection using Austro Engines E4 Manual and Diamond AMM checklist for reference. Installed (7) P/N 5W30LT - Aeroshell, Installed P/N HU615/3x - Oil filter.
2. Drained oil, retained sample for analysis. Removed filter, inspected with no contamination noted. Installed new filter, safety wired and added 7qts Aeroshell Ultra Diesel oil. Installed P/N Blackstone Kit - Oil Analysis.
3. All routine service items performed. Installed P/N WK724-3 - Fuel filter.
4. Inspected engine coolant tank and pressure checked as required.
5. Visually inspected turbo charger and lubricated as required.
6. Inspected exhaust system as required.
7. Examined all belts and wiring with no defect noted.
8. All applicable ADs checked bi-weekly thru this date.
9. Complied with AD2024-19-10 Piston boroscope by boroscope inspection IAW MSBE4-043 with no cracks noted. Next due Tach: 454.9 Installed P/N MSB-E4-043-KIT - MSB-E4-043-KIT.
10. Removed and replaced engine to gearbox dual mass flywheel with serviceable unit. Removed S/N: 27247 Installed S/N: 05762 Installed P/N E4A-73-000-000-KIT - Flywheel Kit.


I certify that this engine has been inspected in accordance with a 100hr Inspection and approved for return to service.

Bryce Hetherly A&P 3959164

Bryce Hetherly

Section 3A: Engine Service and Maintenance Log

Engine - page 1 of 1



Take Flight Aviation LLC · 49 Hangar Road · Montgomery, NY 12549 · 8454574188

N627PS

Hobbs : 653.7

AUSTRO, E4-A, S/N: E4-A-06577

Tach: 455.0

May 19, 2025

Complied with AD2024-19-10 Piston boroscope by boroscope inspection IAW MSBE4-043 with no cracks noted. Next due Tach: 505.0 Installed P/N MSB-E4-043-KIT - MSB-E4-043-KIT.

Functional check of work completed satisfactory

James T. Markey A&P 3166872

Engine page 1 of 1



Take Flight Aviation LLC · 49 Hangar Road · Montgomery, NY 12549 · 8454574188

N627PS

Hobbs: 732.4

Austro, E4A, S/N: E4-A-06577

Tach: 507.8

June 04, 2025

1. Drained oil, retained sample for analysis. Removed filter, inspected with no contamination noted. Installed new filter, safety wired and added 7qts Aeroshell Ultra Diesel oil. Installed P/N Blackstone Kit - Oil Analysis.
2. Performed 100hr engine inspection using Austro Engines E4 Manual and Diamond AMM checklist for reference. Installed P/N HU615/3x - Oil filter, Installed (7) P/N 5W30LT - Aeroshell.
3. All routine service items performed. Installed (1 gal) P/N SPIRAX-S6-GXME75W - Gearbox Oil, Installed P/N WK724-3 - Fuel filter.
4. Inspected engine coolant tank and pressure checked as required.
5. Visually inspected turbo charger and lubricated as required.
6. Inspected exhaust system as required.
7. Examined all belts and wiring with no defect noted.
8. All applicable ADs checked bi-weekly thru this date.
9. Complied with AD2024-19-10 Piston boroscope by boroscope inspection IAW MSBE4-043 with no cracks noted. Next due Tach: 557.8 Installed P/N MSB-E4-043-KIT - MSB-E4-043-KIT.

I certify that this engine has been inspected in accordance with a 100hr Inspection and that this engine has been determined airworthy and approved for return to service.

Bryce Hetherly A&P 3959164

Engine - page 1 of 1



Take Flight Aviation LLC · 49 Hangar Road · Montgomery, NY 12549 · 8454574188

N627PS

Hobbs: 732.4

AUSTRO, E4-A, S/N: E4-A-06577

Tach: 507.8

June 06, 2025

Removed and replaced dual mass flywheel with new as required. Removed S/N: 05762. Installed P/N E4A-73-400-000-KIT - Flywheel Kit S/N: RC2413212.

Run up and functional check of work completed satisfactory

Bryce Hetherly A&P 3959164

THIS PAGE
TOTALS

PREVIOUS
TOTALS

TOTALS
SINCE NEW

CARRY FORWARD to Top of Next Page

ENGINE



Diamond
AUTHORIZED SERVICE CENTER

Take Flight Aviation
49 Hangar Rd Montgomery NY, 12549
845 -457-4188

N627PS

AUSTRO E4-A S/N: E4-A-06577

06/20/2025

Hobbs: 805.1

Tach: 557.9

Complied with AD2024-19-10 Piston borescope by borescope inspection IAW MSBE4-043 with no cracks noted.
Next due Tach: 607.9 Installed P/N MSB-E4-043-KIT - MSB-E4-043-KIT.

Run up and functional check of work completed satisfactory

James T. Markey A&P 3166872

ENGINE



Diamond
AUTHORIZED SERVICE CENTER

Take Flight Aviation
49 Hangar Rd Montgomery NY, 12549
845 -457-4188

N627PS

Austro E4A S/N: E4A-06577

07/01/2025

Hobbs: 871.1

Tach: 606.4

1. Drained oil, retained sample for analysis. Removed filter, inspected with no contamination noted. Installed new filter and added 7qts Aeroshell Ultra Diesel oil. Installed P/N Blackstone Kit - Oil Analysis.
2. Performed 100hr engine inspection I/A/W 14 CFR, part 43, Appendix D, using Austro Engines E4 Manual and Diamond AMM checklist for reference. Installed P/N HU615/3x - Oil filter, Installed (7) P/N 5W30LT - Aeroshell.
3. All routine service items performed. Installed (1 gal) P/N SPIRAX-S6-GXME75W - Gearbox Oil, Installed P/N WK724-3 - Fuel filter.
4. Inspected engine coolant tank and pressure checked as required.
5. Visually inspected turbo charger and lubricated as required.
6. Inspected exhaust system as required.
7. Examined all belts and wiring with no defect noted.
8. All applicable ADs checked bi-weekly thru this date.
9. Complied with AD2024-19-10 Piston borescope by borescope inspection IAW MSBE4-043 with no cracks noted. Next due Tach: 656.4 Installed P/N MSB-E4-043-KIT - MSB-E4-043-KIT.
10. Re-torqued exhaust manifold to spec as required.
11. Removed and replaced engine driven high pressure fuel pump with serviceable unit Total time on serviceable pump 268.3. Removed S/N: 22-08-18-02-000595 Installed S/N: 22-05-17-02-00324. Installed P/N E4A-30-000-BHY - High Pressure Pump System.
12. Removed and replaced waste gate controller clip with new as required. Installed P/N E4A-41-100-801 - Circlip, Spring Loaded.

I certify that this engine has been inspected in accordance with a 100hr Inspection and approved for return to service.

James T. Markey A&P3166872

ENGINE



Diamond
AUTHORIZED SERVICE CENTER

Take Flight Aviation
49 Hangar Rd Montgomery NY, 12549
845 -457-4188

N627PS

AUSTRO E4-A S/N: E4-A-06577

07/22/2025

Hobbs: 840.2

Tach: 656.9

Complied with AD2024-19-10 Piston borescope by borescope inspection IAW MSBE4-043 with no cracks noted.
Next due Tach: 706.9 Installed P/N MSB-E4-043-KIT - MSB-E4-043-KIT.

Functional check of work completed satisfactory

James T. Markey A&P3166872

ENGINE



Take Flight Aviation
49 Hangar Rd Montgomery NY, 12549
845-457-4188

Hobbs: 1004.6 Tach: 703.1 SMOH: 703.1

- I certify that this engine has been inspected in accordance with a 100hr Inspection and approved for return to service.

James T. Markey A&P3166872 *James T. Markey*



Take Flight Aviation
49 Hangar Rd Montgomery NY, 12549
845-457-4188

ENGINE

Hobbs: 1078.2 Tach: 755.2

Complied with AD2024-19-10 Piston borescope by borescope inspection IAW MSBE4-043 with no cracks noted.
Next due Tach: 805.2 Installed P/N MSB-E4-043-KIT - MSB-E4-043-KIT.

Run/Up and leak check of work completed satisfactory

James T. Markey A&P3166872

[illegible]

CARRY FORWARD to Top of Next Page



Take Flight Aviation
49 Hangar Rd Montgomery NY
845-44

N627PS

Austro E4A S/N: E4-A-06577

09/12/2025

Hobbs: 1141.5

Tach: 801.1

TSN: 801.1

1. Performed Annual engine inspection I/A/W 14 CFR, part 43, Appendix D, using Austro Engines E4 Manual and Diamond AMM checklist for reference. Installed P/N HU615/3x - Oil filter, Installed (7) P/N 5W30LT - Aeroshell.
2. Drained oil, retained sample for analysis. Removed filter, inspected with no contamination noted. Installed new filter, safety wired and added 7qts Aeroshell Ultra Diesel oil. Installed P/N Blackstone Kit - Oil Analysis.
3. All routine service items performed. Installed (1 gal) P/N SPIRAX-S6-GXME75W - Gearbox Oil, Installed P/N WK724-3 - Fuel filter.
4. Inspected engine coolant tank and pressure checked as required.
5. Visually inspected turbo charger and lubricated as required.
6. Inspected exhaust system as required.
7. Examined all belts and wiring with no defect noted.
8. All applicable ADs checked bi-weekly thru this date.
9. Complied with AD2024-19-10 Piston borescope by borescope inspection IAW MSBE4-043 with no cracks noted. Next due Tach: 851.1 Installed P/N MSB-E4-043-KIT - MSB-E4-043-KIT.
10. AD2016-23-03 V-band clamp does not apply to aircraft by build date of aircraft and improved V-band clamp installed at manufacture.
11. AD2016-22-08 Auto pilot bridle cable does not apply by aircraft S/N.
12. AD2013-08-21 Turbo charged air pipe does not apply by aircraft S/N.
13. AD2020-22-14 Turbocharger waste gate control rod does not apply by installation of waste gate control rod bridge at date of build.
14. AD2025-02-12 Piston manufacturing deviation does not apply by engine S/N

I certify that this engine has been inspected in accordance with an Annual Inspection at Take Flight Aviation, LLC., and that this engine has been determined airworthy and approved for return to service.

James T. Markey
James T. Markey A&P3166721A

ENGINE



Take Flight Aviation
49 Hangar Rd Montgomery NY, 12549
845-457-4188

N627PS

AUSTRO E4-A S/N: E4-A-06577

10/01/2025

Hobbs: 1214.4

Tach: 851.1

Complied with AD2024-19-10 Piston borescope by borescope inspection IAW MSBE4-043 with no cracks noted.
Pistons expire at 900.0hrs and will need replacement. Installed P/N MSB-E4-043-KIT - MSB-E4-043-KIT.

Run up and functional check of work completed satisfactory

James T. Markey
James T. Markey A&P3166872

Section 3A: Engine Service and Maintenance Log

ENGINE



Take Flight Aviation
49 Hangar Rd Montgomery NY, 12549
845-457-4188

N627PS

Austro E4-A S/N: E4-A-06577

11/04/2025

Hobbs: 1274.8

Tach: 896.2

1. Drained oil, retained sample for analysis. Removed filter, inspected with no contamination noted. Installed new filter, safety wired and added 7qts Aeroshell Ultra Diesel oil. Installed P/N Blackstone Kit - Oil Analysis.
2. Performed 100hr engine inspection I/A/W 14 CFR, part 43, Appendix D, using Austro Engines E4 Manual and Diamond AMM checklist for reference. Installed P/N HU615/3x - Oil filter, Installed (7) P/N 5W30LT - Aeroshell.
3. All routine service items performed. Installed (1 gal) P/N SPIRAX-S6-GXME75W - Gearbox Oil, Installed P/N WK724-3 - Fuel filter.
4. Inspected engine coolant tank and pressure checked as required.
5. Visually inspected turbo charger and lubricated as required.
6. Inspected exhaust system as required.
7. Examined all belts and wiring with no defect noted.
8. All applicable ADs checked bi-weekly thru this date.
9. Removed engine to facilitate piston replacement. Dis-assembled engine and removed time limited pistons and installed kit E4A-72-300-KIT and core replacement kit P/N: E4A-00-M01-KIT. Engine re-assembled, re-installed and serviced to proper level with oil, coolant and gearbox fluid. All work done IAW Austro maintenance manual and Diamond DA40 Maintenance manual. Piston kit installed S/N: 00839. Installation of this kit terminates the repetitive inspection called out in AD2024-19-10. Installed (3) P/N Zerex-G48 - Zerex G48.
10. Removed and replaced all four fuel injectors with new as required. Installed P/N E4A-35-100-000 - Fuel Injector Assy Rev/Lot: RC2200249.

I certify that this engine has been inspected in accordance with a 100hr Inspection has been determined airworthy and is approved for return to service.

Bryce Hetherly A&P3959164

ENGINE



Take Flight Aviation
49 Hangar Rd Montgomery NY, 12549
845-457-4188

N627PS

Austro E4-A S/N: E4-A-06577

12/23/2025

Hobbs: 1424.6

Tach: 996.4

1. Performed 100hr engine inspection I/A/W 14 CFR, part 43, Appendix D, using Austro Engines E4 Manual and Diamond AMM checklist for reference. Installed P/N HU615/3x - Oil filter, Installed (7) P/N 5W30LT - Aeroshell.
2. Drained oil, retained sample for analysis. Removed filter, inspected with no contamination noted. Installed new filter, safety wired and added 7qts Aeroshell Ultra Diesel oil. Installed P/N Blackstone Kit - Oil Analysis.
3. All routine service items performed. Installed (1 gal) P/N SPIRAX-S6-GXME75W - Gearbox Oil, Installed P/N WK724-3 - Fuel filter.
3. Inspected engine coolant tank and pressure checked as required.
4. Visually inspected turbo charger and lubricated as required.
5. Inspected exhaust system as required.
6. Examined all belts and wiring with no defect noted.
7. All applicable ADs checked bi-weekly thru this date.
8. Removed and replaced gear box drain plug seal with new s required.

I certify that this engine has been inspected in accordance with a 100hr Inspection and approved for return to service.

Bryce Hetherly A&P3959164

PREVIOUS TOTALS									
TOTALS SINCE NEW									

CARRY FORWARD to Top of Next Page