

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3YF-1RF

PROPELLER S/N FP10026B

LOGBOOK # 1

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

PROPELLER MAINTENANCE RECORD

Position ONE

PITCH RANGE

Propeller Model PHC-J3YF-1RF

High/Feather

Propeller S/N FP10026B

Start Lock

Blade Design F7693DFB

Low

Blade S/N's

Reverse

No. 1 M24710

No. 2 M24715

Aircraft Manufacturer CIRRUS DESIGN CORP

No. 3 M24718

Aircraft Model SR22

No. 4


S/N 8814


No. 5

Registration N46JG

No. 6

Spinner Assembly Part No.

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
7-27-22	00 N/A	0.0	I have Dynamically Balanced Propeller IAW Hartzell Propeller Owner's Manual 115N Rev. 24 dated Dec/20 Section: 61-00-15 on <u>7-27-22</u> (DATE). The location of the Weight(s) are <u>70 190</u> degree And are <u>24.9 16.3</u> gram(s).   (Sign/Stamp) Cirrus Design Corporation, PC 338CE
PROP MODEL: PHC-J3YF-1RF PROP S/N: FP10026B REG NO: N46JG WORK ORDER: 7296			 Nassau Flyers 1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626
Prop Entries Adjusted static full power RPM to 2670 RPM, no defects noted. Maintenance Release This aircraft, engine, propeller or component(s) on N46JG were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times			DATE: 12/23/2022 A/C TSN: 80.1 PROP TT: 80.1 TACH: 80.1
DATE: 12/23/2022 SIGNED:  Darion McFadden, A&P: 4138120			Work Order: 7296 Printed by EBIS 3 (datcomedia.com)

PROP MODEL: PHC-J3YF-1RF PROP S/N: FP10026B REG NO: N46JG WORK ORDER: 7324			 Nassau Flyers 1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626	DATE: 2/8/2023 A/C TSN: 101.2 PROP TT: 101.2 TACH: 101.2
Prop Entries Cirrus Maintenance Program CMX In-Service Inspection II (100 Hr. Inspection) *Performed a 100 hour inspection of propeller per Cirrus AMM and Cirrus inspection checklists, Chaps 05-20 and 05-30. *Removed propeller spinner and serviced/dressed/painted propeller as need, then reinstalled spinner. Maintenance Release This aircraft, engine, propeller or component(s) on N46JG were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times			Work Order: 7324 Printed by EBIS 3 (datcomedia.com)	
DATE: 2/8/2023 SIGNED:  Syed Rafay Hossain, A&P: 4521779				

7451 (08-08-2023)

Page 1 / 1

MAKE: Cirrus Design Corp
MODEL: S722
S/N: 8814
REG NO: N46JG
PROP MAKE: HARTZELL
PROP MODEL: PHC-J3YF-1RF



Nassau Flyers
1300 New Hwy
Farmingdale, NY 11735

W/O #: 7451
DATE: 08-08-2023
A/C TT: 201.8
A/C Tach: 201.8
Prop TT: 201.8

Propeller Entries

Performed a 100 hour inspection of propeller per Cirrus AMM and Cirrus inspection checklists, Chaps 05-20 and 05-30.
*Removed propeller spinner and serviced/dressed/painted propeller as need, then reinstalled spinner.

Maintenance Release

This aircraft, engine, propeller or component(s) on N46JG were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 08-08-2023

SIGNED:


Darion McFadden
A&P or IA Number: 4138120

WORK ORDER: 7451

Printed by EBIS (EBISCloud.com)

7551 (01-02-2024)

Page 1 / 1

MAKE: Cirrus Design Corp
MODEL: Sr22
S/N: 8814
REG. NO: N46JG
PROP MAKE: HARTZELL
PROP MODEL: PHC-J3YF-1RF



Nassau Flyers
1300 New Hwy
Farmingdale, NY 11735

W/O #: 7551
DATE: 01-02-2024
A/C TT: 299.4
A/C Tach: 299.4
Prop TT: 299.4

Propeller Entries

Performed a 100 hour inspection of propeller per Cirrus AMM and Cirrus inspection checklists, Chaps 05-20 and 05-30.

*Removed propeller spinner and serviced/dressed/painted propeller as need, then reinstalled spinner.... Serviced propeller with NYCO GN3058 grease.

Maintenance Release

This aircraft, engine, propeller or component(s) on N46JG were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 01-02-2024

SIGNED:

Jesse Cardinale
A&P or IA Number: 4534204

WORK ORDER: 7551

Printed by EBIS (EBISCloud.com)

10031 (06-13-2024)

Page 1 / 1

MAKE: Cirrus Design Corp
MODEL: Sr22
S/N: 8814
REG. NO: N46JG
PROP MAKE: HARTZELL
PROP MODEL: PHC-J3YF-1RF



Nassau Flyers
1300 New Hwy
Farmingdale, NY 11735

W/O # 10031
DATE: 06-13-2024
A/C TT: 401.1
A/C Tach: 401.1
Prop TT: 401.1

Propeller Entries

Cirrus Maintenance Program CMX In-Service Inspection II (100 Hr. Inspection)

*Performed a 100 hour inspection of propeller per Cirrus AMM and Cirrus inspection checklists, Chaps 05-20 and 05-30.

*Removed propeller spinner and serviced/dressed/painted propeller as need, then reinstalled spinner.

Maintenance Release

This aircraft, engine, propeller or component(s) on N46JG were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 06-13-2024

SIGNED:

Syed Rafay Hossain
A&P or IA Number: 4521779

WORK ORDER: 10031

Printed by EBIS (EBISCloud.com)

10142 (10-24-2024)

Page 1 / 1

MAKE: Cirrus Design Corp
 MODEL: Sr22
 S/N: 8814
 REG. NO: N46JG
 PROP MAKE: HARTZELL
 PROP MODEL: PHC-J3YF-1RF



Nassau Flyers
 1300 New Hwy
 Farmingdale, NY 11735

W/O #: 10142
 DATE: 10-24-2024
 A/C TT: 502.1
 A/C Tach: 502.1
 Prop TT: 502.1

Propeller Entries

Performed a 100 hour inspection of propeller per Cirrus AMM and Cirrus inspection checklists, Chaps 05-20 and 05-30.
 *Removed propeller spinner and serviced/dressed/painted propeller as need, then reinstalled spinner.

Maintenance Release

This aircraft, engine, propeller or component(s) on N46JG were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 10-24-2024

SIGNED:

Jesse Cardinale
 A&P or IA Number: 4534204

WORK ORDER: 10142

Printed by EBIS (EBISCloud.com)

10235 (04-11-2025)

Page 1 / 1

MAKE: Cirrus Design Corp
 MODEL: Sr22
 S/N: 8814
 REG. NO: N46JG
 PROP MAKE: HARTZELL
 PROP MODEL: PHC-J3YF-1RF



Nassau Flyers
 1300 New Hwy
 Farmingdale, NY 11735

W/O # 10235
 DATE: 04-11-2025
 A/C TT: 599.2
 A/C Tach: 599.2
 Prop TT: 599.2

Propeller Entries

Performed a 100 hour inspection of propeller per Cirrus AMM and Cirrus inspection checklists, Chaps 05-20 and 05-30.
 *Removed propeller spinner and serviced/dressed/painted propeller as need, then reinstalled spinner. Serviced propeller with NYCO GN3058 grease.

Maintenance Release

This aircraft, engine, propeller or component(s) on N46JG were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 04-11-2025

SIGNED:

Jesse Cardinale
 A&P 4534204

WORK ORDER: 10235

Printed by EBIS (EBISCloud.com)

MAKE: Cirrus Design Corp
MODEL: Sr22
S/N: 8814
REG. NO: N46JG
PROP MAKE: HARTZELL
PROP MODEL: PHC-J3YF-1RF



Nassau Flyers
1300 New Hwy
Farmingdale, NY 11735

W/O #: 10382
DATE: 10-06-2025
A/C TT: 698.9
A/C Tach: 698.9
Prop TT: 698.9

Propeller Entries

Performed a 100 hour inspection of propeller per Cirrus AMM and Cirrus inspection checklists, Chaps 05-20 and 05-30.
*Removed propeller spinner and serviced/dressed/painted propeller as need, then reinstalled spinner.

Maintenance Release

This aircraft, engine, propeller or component(s) on N46JG were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 10-06-2025

SIGNED:

Jesse Cardinale
A&P 4534204

WORK ORDER: 10382

Printed by EBIS (EBISCloud.com)

[illegible][illegible]